

Remove Imperfections in Ceramic Tableware

(China, Hotelware, Porcelain, Bone China, Earthenware) with the “Double Bench Beltit” (DBB)

Quick, Safe, Easy & Low Cost DBB Method



Different consumables enable the DBB to overcome rectification problems:

- Rectify faults on ware (surface imperfections)
 - kiln dirt, decal faults, gold flake removal
- Grind “under-glaze” faults prior to glazing
- Polish out without trace and without need for re-glazing most “on-glaze” and “in-glaze” faults
- Select, polish and grade in one operation, without putting down the piece of ware

Exceedingly Reliable - 10 year guarantee

High Performance - Can be operated 24 hours / 7 days a week

Low Cost & Easy to Operate. Inexperienced operators quickly become expert at reclaiming ware. The DBB is very safe and has low noise & vibration levels.

Low amount of electricity required.

With a 14 x 760mm grinding belt:

- lowest speed @ 1,000rpm - 0.5 AMPS - highest speed @ 7,500rpm - 1.3 AMPS

Long life, high quality consumables & spare parts are available from Hygan

Since 1986 the DBB has enabled the World's Ceramic Tableware Producers to **achieve the very highest prices for their ceramic tableware** by rectifying faults that occur during the manufacturing process.

Dave Withington
Technical Sales Manager (07964 993 485), sales@hygan.com

Hygan Products Ltd.
Kingscroft Works, Stoke Old Road, Hartshill
Stoke-on-Trent. ST4 6ES UK

Tel 01782 613936
Fax 01782 711614
www.hygan.com



The DBB is designed and manufactured by Seco Engineering Co. Ltd. in the UK.